

Catalyst A/C Service Report From 10/25/2024

Job #4824793

A/C Maintenance Checklist

Customer Name

Please list customer name

Terry Donovan

CUSTOMER SERVICE LOCATION:

Please list address of service

2551 Barcelona Avenue, Fort Myers, FL 33905

System Overview

Overall System Health Score

9

Top Concerns

No major concerns at this time

Indoor

Air Handler

Picture of Existing Air Handler

Equipment Age

Age of Air Handler

2014

Thermostat

Current and capable of utilizing all of the system's features

Duct Leakage

No or insignificant amounts of air leakage

Evaporator Coil/Corrosion (Include picture)

No leaks or visible corrosion

Microbial Growth and Bacteria

No visible bacteria

Filtration System

Standard 1 Inch

Was filter changed?


YES

Condensate Pump

N/A

Pump Tubing

N/A



Drain Pan

Good Condition

Float Switch

Code Compliant with backup

Blower Motor

Functional with no signs of leakage or high power usage

Blower Run Capacitor

Functional with optimal readings

Blower Amps

1.2

Attic Insulation Level (include picture)

R30-R38 (Code Compliant, but not optimal)

Outdoor**Condenser**

Picture of Existing Condenser

Equipment Age

Age of Condenser Unit

2014

Dual Run Capacitor (include picture of cap specs and meter)

Functional with optimal readings

Contactors

Good Condition

Has Surge Protector?

N/A

Disconnect Box

Good Condition

Electrical Wiring & Terminals

Pass

Condenser Coil

Pass

Refrigerant Pipe Insulation

Good Condition

Unit Level

Pass

Compressor amp draw under load (RLA)

14.1

Condenser fan motor amps (RLA)

2.2

Power Is Restored And System Is Running YES